pproved For Release 1999/09/08 CIA-RDP82-00457R0002008 10005-9

JGENCE GROUP

25X1A2g

COUNTRY China DATE: 25X1A6a

MFO.

SUBJECT

ORIGIN

Economic Information: Tientsin-Tangku Highway

DIST. 21 January 1947

25X1A6a

PAGES 1

25X1X6

"LIBRARY COPY

SUPPLEMENT

1. The highway appears to be in the best condition since April 1946. The grading and placing of gravel jobs are already complete for the first few miles on the Tientsin end and the section seems to have a comparatively smooth surface, which is holding up well. Work is progressing slowly; however, several steam rollers were seen to be working. Approximately 1,000 to 2,000 feet of gravel were laid and rolled on the date of observation. The section of the road entering Tangku continues to be the worst stretch.

2. The new bridges on the highway are still being worked upon, but not one has been completed. It appears that the highway commission changed its plan, previously reported, the make the bridges wooden; for in addition to wooden piling already sunk, round prefabricated concrete piling the size of a small oil drum is being placed and concrete slabs laid across these before the wooden decking or road surface is laid. While work was observed to be actually in progress on almost all of the bridges, it is proceeding very slowly.

> Document No. NO CHANGE in Class ☐ DECLASSIFIED Class. CHAN TO: TS 4 Apr 77 5 APR 1978 By: